



PETROCHEMICALS (MALAYSIA) SDN. BHD.

(Company Registration No: 12215-H)

GST No: 001427636224

HEAD OFFICE: PLO 408, Off Jalan Pekelling, Pasir Gudang Industrial Estate, 81700 Pasir Gudang, Johor, Malaysia.

Tel: +607-2596300 Fax: +607-2596320

Incident at Styrene Monomer Tank

At around 17:00pm on 23rd August 2023, there was Styrene Monomer Tank (SM Tank) Releasing Chemical Vapors due to tank ruptured. It triggered strong chemicals smell spread around our neighboring companies and residents.

With the assistance and supports from BOMBA and other relevant authorities, especially BOMBA HAZMAT unit, we sprayed chemical foam and water to cooling off the SM Tank. The counter measures have reduced Chemical smell and contained within the compound around 8:30p.m.

The chronology of Incidents as follows

1. Incident Location: Petrochemicals (M) Sdn Bhd Styrene Monomer Tank (SM Tank)
2. Incident summary
 - SM Tank pressure increase damages the top plate and causes SM vapor release.
 - The SM tank is isolated and is being cooled off by sprinkling water to prevent the spread of damage.
 - Under the supports from BOMBA HAZMAT Team, foam-extinguishing agent is injected from the top plate to prevent released of SM vapor.
3. Damage
 - No human casualties and injury
 - The cause of the incident and other damages to be investigated

We are keenly aware that this incident has caused significant concern and inconvenience to neighboring residents. We are now focusing on uncovering the precise details of what has happened so that we can address all issues arising from this matter resolutely and appropriately

Yours sincerely,

SHE Department